HABS No. IA-76

Lee County Courthouse 701 Avenue F. Fort Madison Lee County Iowa

HABS, 10WA, 56-FTMAD

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Heritage Conservation and Recreation Service
Department of the Interior
Washington, D.C. 20243

nited States Department of the Interior eritage Conservation and Recreation Service ashington, D.C. 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY

DATE

8/1/80

ARCHITECTURAL DATA FORM

56 - FTMAD.

STATE	COUNTY	TOWN DR VIC	INITY
IOWA	LEE	FORT MADIS	NC
HISTORIC NAME OF STRUCT	URE (INCLUDE SOURCE FOR	NAME)	HABS NO.
LEE COUNTY COURTHOUSE		. :	IA-76
SECONDARY OR COMMON NAM	ES OF STRUCTURE		
SECONDARY ON COMMON MAN	_3 OF STRUCTURE		•
	IBE LOCATION FOR RURAL	SITES)	
701 Avenue F.	•		
DATE OF CONSTRUCTION (ACLUDE SOURCE) (ARCHITE	CT(S) (INCLUDE SOURCE)	
1841-42	•	•	
GLOW FLOWER (AGGIVETON	I DATE OF COLUMN	THE COLCINAL HEE OF S	י בסוור דווסב
This structure is one	URAL AND HISTORICAL, INC of the finest Greek Reviv	LOVE ORIGINAL USE OF 3	(NOC LONE)
of the oldest survivin	g courthouses	al buildings in the stat	ie and one
	<u> </u>		
		•	
STYLE (IF APPROPRIATE) Greek Revival		•	- <u> </u>
MATERIAL OF CONSTRUCTION	I (INCLUDE STRUCTURAL SY	(STEMS)	
Constructed of brick	, (1.102022 21.1120101112 21.	- · · · · · · · · · · · · · · · · · · ·	,
		<u> </u>	
The Sourthouse management	STRUCTURE (SKETCHED FLO	OR PLANS ON SEPARATE PA	GES ARE ACCEPTABLE
is height. It is cappe	s 50' (three-bay front) xed with a gable roof, the	. 100 (four pays) and is : ridge perpendicular to	two stories
EXTERIOR FEATURES OF NOT			
The structure, built in	n the temple plan, contai	ns a tetrastyle portico	of brick
Doric columns, capped) facades.	oy a simple pedimented ga	ble. The entablature ru	ns. on all
racades.			
INTERIOR FEATURES OF NOT	E (DESCRIBE FLOOR PLANS	, IF NOT SKETCHED)	
Containing a central ha	all plan, the courtroom i	s located at the south e	nd of the
second floor.			
		·	•
MAJOR ALTERATIONS AND AC	OITIONS WITH DATES		
A post-Civil War cupola	was destroyed by fire i	n 1911. There has been	additions to
the rear, and extensive	interior alterations		·
PRESENT CONDITION AND US	:6		
Excellent, presumably a	:		
OTHER INFORMATION AS APP	ROPRIATE		
	•		
	•	~	
OURCES OF INFORMATION	INCLUDE LISTING ON NATI	ONAL REGISTER, STATE RE	GISTERS, ETC.)
1.6			
onank, westey 1., The	Iowa Catalog: Historic A	merican Buildings Survey	r

University of Iowa Press, Iowa City, 1979.

Kent R. Newell, Historic American Buildings Survey

COMPILER, AFFILIATION